S	ervice Bulletin	BRIGGS.STRATTON	<u>Allmand</u>
To:	Notified Customers	Critical Correction - Action & Response Required Immediatly	
		Action Required - Fix, No Report	
Bulletin Number:	SB 22-0013-MH-1MBTU		
Date Of Notice:	10/7/22	If Encountered - Correct If Issue is Found	
Subject:	Maxi Heat circulation cap switch upgrade	Information Only	\checkmark
Product Line:	Maxi Heat 1MBTU	monitation only	
		Authorized Labor Charges For This Bulletin:	
Model:	Heater	No labor & No parts	
Serial Numbers:	36-000001 through 36-000796	Part Numbers Required To Correct This Bulletin	ו:
Expiration Date:	No Expiration	Kit Part Number 124434	

Description or Summary of improvement:

Heaters without air recirculation duct switches allow the unit to operate with the air caps left on. If the caps are left on, this will lead to increased cabin temperatures and the burner cycling more frequently. It will also increase the chances of servicing the burner more often.

Correction and Instructions:

Adding this update will help to improve air circulation and further extend the life of the heater. When adding switches to the air recirculation duct, this will ensure the caps have to be removed when attempting to operate the burner. Please review page two for additional information.

CONTACT INFORMATION: FOR ADDITIONAL CLARIFICATION OR FURTHER INSTRUCTIONS, PLEASE CONTACT THE FOLLOWING: ALLMAND SERVICE TEAM AT (308) 995-3431

Service Bulletin






SB 22-0013-MH 1MBTU Air Recirculation Duct Switches

Step 1: Opening the air caps will verify if the unit was built with switches.

Step 2: Once the caps are removed, check the upper left corner of the inlet to verify if switches were installed.









SB 22-0013-MH 1MBTU Air Recirculation Duct Switches

Step 3: Kit 124434 is needed if your unit does not have switches installed. Each kit will include installation instructions, schematics and all the parts needed for the update. Please contact the Allmand parts department at 800-562-1373 or email the parts team at Allmand.parts@basco.com to purchase the retro kits

Note: There is no need for the retro kit if the unit already has switches installed.