Service Bulletin

Notified Customers
SB 22-0014-NL-GR
10/10/22
Fuse & Fuse holder update
Nite Lite GR Series
GR Air Cooled 3KW (Yanmar L70W)
25-000001 - 25-002620
No Expiration

Αποι		Allmand°
	Critical Correction - Action & Response Required Immediatly	
	Action Required - Fix, No Report	
	If Encountered - Correct If Issue is Found	
	Information Only	~
	Authorized Labor Charges For This Bulletin: No Labor & No parts	
	Part Numbers Required To Correct This Bulletin	1:
	Kit Part Number 124437	

Description or Summary of Improvement:

The 20 amp glass fuse between the regulator and starter has been upgraded to a different style of fuse. The new style fuse will help with less movement when vibration occurs. This also helps to reduce the amount of failures with the old style fuse.

BRIGGS&STR

Correction and Instructions:

Remove the old assembly by disconnecting the wires from regulator to the starter. Replace with new wire and fuse holder from kit 124437. Follow the instructions and schematic that come with kit 124437.

CONTACT INFORMATION: FOR ADDITIONAL CLARIFICATION OR FURTHER INSTRUCTIONS, PLEASE CONTACT THE FOLLOWING: ALLMAND SERVICE TEAM AT (308) 995-3431

Service Bulletin





SB 22-0014-NL-GR Fuse & fuse holder update

Example A: In the photo below is the original style. If your unit is set up with this same assembly, you can update it with kit 124437.

Example B: Is the new updated fuse assembly.



